

SAFETY INSPECTION

Page 1 of 2

1. LICENSEE Aetos Corporation 3301 Colley Avenue Norfolk, Virginia 23508-3016		2. REGIONAL OFFICE REGION II U S NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323	
3. DOCKET NUMBER(S) 030-33174	4. LICENSE NUMBER(S) 45-25251-01ND	5. DATE OF INSPECTION 9/14/93	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation by the inspector. The findings as a result of this inspection are as follows:

<input type="checkbox"/>	1. Within the scope of this inspection, no violations were observed.
<input type="checkbox"/>	2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
<input checked="" type="checkbox"/>	3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a NOTICE OF VIOLATION , which is required to be posted in accordance with 10 CFR 19.11.
<input type="checkbox"/>	A. _____ was not properly posted to indicate the presence of a _____, 10 CFR 20.203(b),(c),(d),(e) or 34.42.
<input type="checkbox"/>	B. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____.
<input type="checkbox"/>	C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____.
<input type="checkbox"/>	D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
<input type="checkbox"/>	E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____.
<input checked="" type="checkbox"/>	F. <u>License had not determined that their dose calibrators were accurate in that data collected on 8/11/93 was not analyzed until 9/14/93. (Item 10.4 of Application + License Condition 26)</u>

150010 9311160062 930914
PDR ADDCK 03033174
C PDR

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE <i>[Signature]</i>	DATE 9-14-93	SIGNATURE - NRC INSPECTOR <i>[Signature]</i>	DATE 9/14/93
--	---------------------	---	---------------------

SAFETY INSPECTION

Page 2 of 2

1. LICENSEE

Aetos Corporation
3301 Colley Avenue
Norfolk, Virginia 23508-3016

2. REGIONAL OFFICE

REGION II
U S NUCLEAR REGULATORY COMMISSION
101 MARIETTA STREET NW SUITE 2900
ATLANTA GA 30323

3. DOCKET NUMBER(S)

030-33174

4. LICENSE NUMBER(S)

45-25251-01100

5. DATE OF INSPECTION

9/14/93

3. (Continued)

G

Failure to determine, by methods listed in Item 10.12a of the Application, that Newport News General Hospital was authorized to receive Tc-99m before transferring 29.66 mCi of Tc-99m to Newport News General Hospital on 9/9/93, (License Condition 26 and Item 10.12a of Application)

H

I

4. The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

A

Section 206 of Energy Reorganization Act not posted as required by 10 CFR 21.6

B

C