VERMONT YANKEE NUCLEAR POWER CORPORATION



Ferry Road, Brattleboro, VT 05301-7002

ENGINEERING OFFICE 580 MAIN STREET BOLTON, MA 01740 1508) 779-6711

January 24, 1994 BVT 94-09

U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Attn: Document Control Desk

References:

a)

License No. DPR-28 (Docket No. 50-271)

Dear Sir:

Subject:

Vermont Yankee 1933 Inservice Inspection-Repair/Replacement Reports

In accordance with Article IWA-600 of Section XI of the ASME Boiler and Pressure Vessel Code, we hereby submit the Vermont Yankee Inservice Examination Report (NIS-1) and the Repair and Replacement Report (NIS-2). These reports describe the inservice examinations performed during the period September 1, 1993 through October 27, 1993 and the repairs and replacements during the period September 1, 1993 through January 23, 1994. Vermont Yankee's third ten-year interval began September 1, 1993.

We trust that the information provided is adequate; however, should you have any questions or require additional information, please do not hesitate to contact us.

Very truly yours,

Vermont Yankee Nuclear Power Corporation

Robert J. Wanczyk

Plant Manager

/dm

cc:

USNRC Region 1 Administrator USNRC Resident Inspector, VYNPS USNRC Project Manager, VYNPS

A047

9402020317 940124 PDR ADDCK 05000271 PDR