Duke Power Company Catawba Nuclear Station P.O. Box 256 Clover, SC 29710



DUKE POWER

October 11, 1990

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Subject: Catawba Nuclear Station

Docket No. 50-414 LER 414/90-S01

Gentlemen:

During the Catawba Unit 2 EOC3 refueling outage, the SSF was in degrade when Mode 3 was entered. This required compensatory action to be taken to post the Nuclear Service Water (RN) Pumphouse with a security officer. Because of a failure to communicate this need from the Operations group to the Security group, this action was not taken. This event will be the subject of an enforcement conference the week of November 5, 1990.

At this time, we request an extension to October 19, 1990 for submittal of this report. This extension period would provide us with the time necessary for additional investigation into this event to determine root causes, necessary corrective actions to be taken and thoroughly review prior to submission of this report.

Thank you in advance for your consideration in this matter.

Very truly yours,

J. W. Hampton Station Manager

ken\EXT.LER

xc: Mr. S. D. Ebneter
Regional Administrator, Region II
U. S. Nuclear Regulator Commission
101 Marietta Street, NW, Suite 2900
Atlanta, GA 30323

M & M Nuclear Consultants 1221 Avenues of the Americas New York, NY 10020

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339 American Nuclear Insurers c/o Dottie Sherman, ANI Library The Exchange, Suite 245 270 Farmington Avenue Farmington, CT 06032

Mr. K. Jabbour U. S. Nuclear Regulatory Commission Office of Nuclear Reactor Regulation Washington, D. C. 20555

Mr. W. T. Orders NRC Resident Inspector Catawba Nuclear Station

00420

9010170229 901011 PDR ADOCK 05000414 S PDC JE22