

SAFETY INSPECTION

1. LICENSEE  
ATLANTIC RICHFIELD COMPANY  
ARCO ALASKA, INC.  
P.O. Box 100360  
Prudhoe Bay Safety Dept.  
Anchorage, Alaska 99510

2. REGIONAL OFFICE

U. S. Nuclear Regulatory Commission  
Region V  
1450 Marais Lane, Suite 210  
Walnut Creek, CA 94596

3. DOCKET NUMBER(S)

030-15092

4. LICEN/DET NUMBER(S)

50-18441-01

5. DATE OF INSPECTION

9/7/90

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The Inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.  
**THIS IS A NOTICE OF VIOLATION** which is required to be issued in accordance with 10 CFR 10.11.

- A. \_\_\_\_\_ was not properly posted to indicate the presence of \_\_\_\_\_ or \_\_\_\_\_ 10 CFR 20.303(b), (c), (d), (e) or 20.40.
- B. Containers located \_\_\_\_\_ labeled to indicate the presence of radioactive material. 10 CFR 20.303(h)(1), or (h)(2).
- C. \_\_\_\_\_ of \_\_\_\_\_ frequencies. 10 CFR \_\_\_\_\_ of \_\_\_\_\_ Licensed Condition Number \_\_\_\_\_ of \_\_\_\_\_ tested sources were not performed at the proper frequency.
- D. Records of \_\_\_\_\_ 10 CFR \_\_\_\_\_ or \_\_\_\_\_ Licensed Condition Number \_\_\_\_\_ were not properly maintained.
- E. Documents were not properly posted or otherwise made available. 10 CFR 10.11.
- F. Reports or notifications of \_\_\_\_\_ with 10 CFR \_\_\_\_\_ or \_\_\_\_\_ Licensed Condition Number \_\_\_\_\_ were not made in accordance.
- G. Condition 10 License Condition 12, Silverbridge had not been used since Oct. 1982 although licensed material had been used
- H. \_\_\_\_\_
- I. \_\_\_\_\_
- J. \_\_\_\_\_
- K. \_\_\_\_\_

I hereby state that within 30 days the actions described by me or the Inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 3.301. No further response will be submitted unless required by the NRC.

  
JOHN A. JOHNSON  
DIRECTOR - INSPECTION

9-24-90  
DAY

T. R. [Signature]  
DATE

10/1/90  
DATE

9010230127 900924  
REG5 LIC30  
50-18441-01 PNU

ORIGINAL TO LICENSEE

10/1/90  
REOY