## नियः Nuclear

PROCEDURE INSTRUCTION MEMO UNIT 1 PROCEDURES

> CORRECT ADDRESS IF NECESSARY

RETURN TO: Betty Nash PROCEDURE DISTRIBUTION CONTROL

**ROOM 150** 

PDR

UNIT 2 ADMIN. BLDG.

Date 7-7-82

DOC ID 0255z

flied of Due Keneton Ry H. R. Denton

Please update your procedure file with the attached procedures listed below, destroy the superseded procedures, and post your Waster Procedure Index accordingly. Also please sign the acknowledgment at the bottom of this memo and return to Betty Nash, Room 130, Procedures Distribution Control, Unit 2

Procedure No.	Rev.	PCR No.	Instructions/Commer	nts
1004.1		1-MD-12-006		
1004.2	_	1-10-12-106		
1004.3		1-nD-82-000		
1004.4		-MD-10-006		
1004.15	2 /	MD-83-005	7	
	= :		(10 Copie 7 la	
				_ X005
ADDITIONAL THE	TO INTTONIC	MACITE .		
ADDITIONAL INS	THU TUNS!	CIO. T	Q.	
s my	The same	Destrice	mis.	
		- 1		
I hereby	edence) edne	e receipt of the	items above and have comp	Mad with
the instruction	ns.	c research of the	TOMS EDUYE EID TRYE COM	ALLI
	Signature)		(Ext. No.)	(Date)