

OCT 18 1990

West Shore Hospital  
ATTN: Burton Parks, Administrator  
1465 East Parkdale Avenue  
Manistee, MI 49660

License No. 21-16277-01  
Docket No. 030-10713  
EA 90-172

Gentlemen:

This refers to the special safety inspection conducted by Messrs. B. A. Parker and P. F. McKee of this office on September 27, 1990, in response to a diagnostic misadministration involving approximately 175 millicuries of a technetium-99m radiopharmaceutical and to the discussion of our findings with Ms. Sheryl Wygant and members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appear to be in violation of NRC requirements. The inspectors also expressed concern with regard to the management oversight of your licensed program. You will be notified by separate correspondence of our decision regarding enforcement action based on the findings of this inspection. No written response is required until you are notified of the proposed enforcement action.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by C. E. Norelius"

Charles E. Norelius, Director  
Division of Radiation Safety  
and Safeguards

Enclosure: Inspection Report  
No. 030-10713/90001(DRSS)

IE07  
111

cc w/enclosure:  
DCD/DCB(RIDS)  
P. F. McKee, NRR

bcc w/enclosure:  
J. Lieberman, OE  
J. Goldberg, OGC  
R. Cunningham, NMSS

RIII  
BAP  
Parker  
10/17/90  
155

RIII  
GLS  
Caniano  
10/17/90

RIII  
Grobe  
10/17

COPY FOR  
EA 90-172  
RIII  
C. E. Norelius  
Pederson

yes  
RIII  
Norelius  
10/17

9010250235 901018  
REG3 LIC30  
21-16277-01 PDC