Hazelton Laboratories America, Inc. ATTM: Mr. R. Conway, Corporate Vice President 3301 Kinsman Blvd Madison, WI 53707 License No. 48-11805-02 Docket No. 030-18286

Gentlemen:

This refers to the routire safety inspection conducted by Ms. T. L. Simmons of this office on August 27-29, 1990, of activities authorized by NRC Byproduct Material License No. 48-11805-02 and to the discussion of our findings with you and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated April 19, 1989, regarding apparent violations found during our February 15 and 17, 1989 inspection. We have no further questions regarding these matters.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

William H. Schultz, Chief Nuclear Materials Safety Section 1

Enclosure: Inspection Report No. 030-18286/90001(DRSS)

cc w/enclosure: DCD/DCB(RIDS)

RIII Simmons/1h RITI Wals Schultz 10-12-90

IE 07

REG3 LIC30 48-11805-02 PNU