

APPENDIX B

U. S. NUCLEAR REGULATORY COMMISSION  
REGION IV

Report: 82-~~92~~

License: 35-15194-01

Locket: 30-08719

Priority: II Category: C1

Licensee: Globe X-Ray Services, Inc.  
8441 South Union  
Tulsa, OK 74132

Meeting Conducted: June 16, 1982

Report Prepared by: C. A. Hooker 6/22/82  
C. A. Hooker, Radiation Specialist Date

Approved by: R. J. Everett 6/25/82  
R. J. Everett, Chief, Materials Radiation Protection Section Date

Meeting Summary

Meeting held June 16, 1982 (Report 30-08719/82-02)

An Enforcement Conference was held by telephone to discuss the findings of the NRC inspection conducted on May 26-27, 1982. The violations were detailed by the Region IV staff and the licensee responded to each item. The meeting involved one man-hour by two NRC personnel.

Results: The NRC staff presented five violations of NRC requirements. The licensee responded as to his understanding of the items of violation. The licensee described the corrective actions that will be taken to bring him within full compliance. The NRC staff expressed concern as to nature and number of violations and summarized the enforcement options available. The NRC staff stated that a letter with the Notice of Violation would be sent to the licensee and the licensee's written response would be carefully reviewed to determine the need for additional enforcement action.

DETAILS

Persons Participating in the Meeting

a. Globe X-Ray Services, Inc.

R. V. Ozmun, President  
Mrs. R. V. Ozmun, Secretary

b. NRC-RIV

R. J. Everett, Chief, Materials Radiation Protection Section  
C. A. Hooker, Radiation Specialist