



Commonwealth Edison
Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

July 28, 1982

Mr. James G. Keppler
Regional Director
Office of Inspection and Enforcement
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station
Docket No. 50-295/DPR-39
Technical Specification, Section 6.6.2

Dear Mr. Keppler

Enclosed please find Reportable Occurrence Report No. 50-295/82-23 for Zion Generating Station.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.b.3 which states that observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems require a 30 day written report.

Very truly yours,

K. L. Graesser
Superintendent
Zion Station

cc: J. Waters

Enclosure: Reportable Occurrence Report No. 50-295/82-23

8208050310 820728
PDR ADOCK 05000295
S PDR

JUL 30 1982

LED