

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 P A P B S 2 2 0 0 - 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 _____ (5)

LICENSEE CODE

LICENSE NUMBER

LICENSE TYPE

CAT 58

CON'T

01 REPORT SOURCE L 8 0 5 0 - 0 2 7 7 7 0 7 0 9 8 2 8 0 7 1 6 8 2 9

REPORT SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a daily surveillance test, the operator observed a discrepancy
03 between the indication of 1 of the 4 'A' main steam line high flow trip
04 transmitters (dPIS-116B) and the other 3. Investigation found that
05 the instrument had an open equalizing valve. Instrument dPIS-116B is
06 part of a 1 out of 2 twice trip logic to initiate Group I valve
07 isolation in the PCIS upon detection of high steam flow. All
08 redundant instrument channels were operable.

09 SYSTEM CODE S D 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE V A L V X 14 COMP. SUBCODE F 15 VALVE SUBCODE X 16

17 LER/NO REPORT NUMBER 8 2 21 22 SEQUENTIAL REPORT NO. 0 1 6 24 26 OCCURRENCE CODE 0 1 28 29 REPORT TYPE T 30 REVISION NO. 0 32

ACTION TAKEN X 18 FUTURE ACTION H 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 37 40 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 3 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The equalizing valve had been left open as a result of instrument
11 work done during the outage. The instrument check following previous
12 event (LER No. 2-82-15/1T) did not detect the open valve. Upon
13 detection it was immediately closed. A valve check was immediately done
14 to verify proper valving. The importance of proper valving was re-emphasized.

15 FACILITY STATUS C 28 % POWER 0 9 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

16 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES NUMBER 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

18 PERSONNEL INJURIES NUMBER 0 0 40 DESCRIPTION N/A 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

8208050325 820716
PDR ADOCK 05000277
S PDR

NRC USE ONLY

NAME OF PREPARER

M. J. Cooney

PHONE (215) 841-5020