

July 23, 1982

Log No. K82-1127 FILE: RR 2 (NP-33-82-35)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 82-031 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: June 25, 1982

Enclosed are three copies of Licensee Event Report 82-031 with a supplemental information sheet, which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Teny Domerray

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station

TDM/1mr

Enclosure

cc: Mr. Richard DeYoung, Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management and Program Analysis Encl: 3 copies

Mr. Walt Rogers NRC Resident Inspector Encl: 1 copy

8208050455 820723 PDR ADOCK 05000346