

NOV 6 1990

In Reply Refer To:
License: 35-26864-01
Docket: 030-29694/90-01

Tulsa Diagnostic & Imaging Center
c/o Tulsa Nutrition & Weight Clinic
ATTN: Nicholas E. Moorad, M.D.
General Partner
5215 East 71st Street, Suite 900
Tulsa, Oklahoma 74136

Gentlemen:

This refers to the attempt by Mr. Selvan Rajendran on August 23, 1990, to obtain the necessary information to terminate your Byproduct Materials License 35-26864-01 for Tulsa Diagnostic & Imaging Center (TDIC) at the above address. The Nuclear Regulatory Commission has been in contact with you to terminate your license since July 21, 1988. The chronology of events are as follows:

1. On July 21, 1988, Mr. Charles Cain of NRC was contacted by Mr. John Geyer to inform NRC that TDIC was filing for bankruptcy. Mr. Cain informed Mr. Geyer of the procedures he must follow to terminate the license properly.
2. On April 25, 1989, Ms. Billie Gruszynski of NRC contacted Dr. Nicholas Moorad regarding the termination of the license. Ms. Gruszynski sent NRC Form 314 to Dr. Moorad. Dr. Moorad stated that he would fill out the form to terminate the license.
3. On June 1, 1989, Mr. G. Michael Vasquez contacted Mr. Gary Tarter regarding the status of the termination. The NRC on June 7, 1989, sent a letter to Mr. Tarter with an additional NRC Form 314 and a self addressed envelope.
4. On March 30, 1990, Mr. Wes Holley attempted to have the 314 signed in person at 3345 South Harvard Avenue, Tulsa, Oklahoma. Mr. Gary Tarter was not available; therefore, Mr. Holley left the form with the secretary to be completed by Mr. Tarter when he returned to the office.
5. On August 23, 1990, Mr. Selvan Rajendran obtained the signed NRC Form 314 from Dr. Moorad at the above address.

Mr. John Geyer was the technologist, Mr. Gary Tarter was the administrator, and Dr. Nicholas E. Moorad was one of the general partners of the firm.

*RIV:NMLS
SRajendran:ch
/ /

C:NMLS *WLF*
WLFisher
11/21

ID:DRSS
ABBeach
11/5/90

*Previously concurred

9011130040 901106
REG4 LIC30
35-26864-01 PNU

110
IE-07

This letter documents the difficulty the NRC had in obtaining the necessary information to terminate the license. As stated above the attempt was started in July 1988 and finally ended in August 1990. The NRC has expended numerous hours and an abundance of manpower to obtain this information and, therefore, you may be subject to inspection fees.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and your response to this letter will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,
Original Signed By:
LAWRENCE A. YANDELL

A. Bill Beach, Director
Division of Radiation Safety
and Safeguards

cc:
Oklahoma Radiation Control Program Director

bcc w/copy of licensee letter:
DMB - Original (IE-07)
RDMartin
ABBeach
LAYandell
MRodriguez, OC/LFDCB (MS 4503)
CLCain
WLFisher
SRajendran
NMSIS
MIS System
RIV Files (2)
RSTS Operator