

NOTICE OF VIOLATION

Mid-American Inspection Services, Inc.
Gaylord, Michigan

Docket No. 030-31160
License No. 21-26060-01

As a result of the inspection conducted on October 11, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, (1989) (Enforcement Policy) the following violations were identified:

1. License Condition No. 11 states that only listed individuals are authorized by this license to act as radiographers as defined in 10 CFR 34.2.

Contrary to the above, on numerous occasions, since approximately October 1, 1990, an individual not listed in License Condition No. 11 acted as a radiographer.

This is a Severity Level IV violation (Supplement VI).

2. 10 CFR 34.33(c) requires that pocket dosimeters be checked at periods not to exceed one year for correct response to radiation.


Contrary to the above, as of the date of this inspection, the licensee failed to conduct a check for correct response to radiation on a dosimeter, serial number 5090160, since June 21, 1989 which was in use on the day of the inspection.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) the corrective steps that have been taken and the results achieved; (2) the corrective steps that will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

10/24/90


Roy J. Caniano, Chief
Nuclear Materials Safety
Section 2

9011130205 901024
REG3 LIC30
21-26060-01 PIC