OCT 2 6 1990

Leeco Diagnostics, Inc. ATTN: Mr. Rod Raynovich Chief Executive Officer 24475 W. 10 Mile Road Southfield, MI 48034 License No. 21-18294-01 Docket No. 030-14802 License No. 21-18294-02G Docket No. 030-14801

Gentlemen:

This refers to the special safety inspection conducted by Mr. J. L. Lynch of this office on September 26, 1990, of activities authorized by NRC Byproduct Material Licenses Nos. 21-18294-01 and 21-18294-02G and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.

The inspection was conducted in response to an allegation received by the NRC on July 2, 1990. The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, independent measurements and interviews with personnel.

During this inspection, certain of your activities under License No. 21-18294-01 appeared to be in violation of NRC requirements, as specified in the enclosed Appendix and a written response is required. No violations were identified for License No. 21-18294-02G.

In accordance with $10\ \text{CFR}\ 2.790$ of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely, John A. Grobe, Chief Nuclear Materials Safety Branch

Enclosures:

1. Notice of Violation

2. Inspection Reports

No. 030-14802/90001(DRSS); No. 030-14801/90001(DRSS)

cc w/enclosures: DCD/DCB (RIDS)

LYNCH/da 190

Dante Capaldi, Ph.D. - RSO

bcc: D. Funk (RIII)

RIII

CANIANO

PROBE

9011130208 901026 REG3 LIC30 21-18294-01 PDC TE 07