


FULL SERVICE WIRELINE

P. O. Box 62
Henryetta, Oklahoma 74437

30-19574



June 7, 1982

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

GLEN D. BROWN:

Your letter of 07 May 1982 the following corrections have been made.

1. License Amendment to possess a Gamma Industries Model NBHP Source has been received.
2. All sealed sources have been leak tested.
3. A. Survey instruments have been calibrated.
b. Monthly surveys of storage building and vehicles are being made.
c. Radioactive monitoring form 100 are being maintained.
4. A. 7 A package certification has been received.
b. Special form certification has been received.
5. A Notice has been posted specifying where required documents may be examined.
6. Form NRC-3 has been posted.

The above steps have already been taken.

A monthly reminder file for instrument calibration and leak test due dates to prevent overrun of instrument cal and leaktest time has been implemented.

Glen R. Cook
GLEN R. COOK
RADIATION SAFETY OFFICER

8208060192 820702
NMS LIC30
35-19736-01 PDR