

ENCLOSURE 3 UNITED STATES NUCLEAR REGULATORY COMMISSION REGION I 631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

MAY 1 9 1982

Docket No. 50-322

DESIGNATED ORIGINAL. Certified By____ Martin

Long Island Lighting Company ATTN: Mr. M. S. Pollock Vice President - Nuclear 175 East Old Country Road Hicksville, New York 11801

Gentlemen:

Subject: Systematic Assessment of Licensee Performance (SALP)

The NRC Region I SALP Review Board met on April 30, 1982 and evaluated the performance of licensed activities at the Shoreham Nuclear Power Station. The Board SALP report of our assessment is enclosed.

The engineering and design area is considered an area of weakness requiring additional NRC and Long Island Lighting Company management attention. Particular areas of concern are the conformance of the plant as constructed to the Final Safety Analysis Report and the prompt correction and prevention of identified problems.

We will meet with you on May 21, 1982 to discuss our assessment, your plans to improve performance, and any comments you may have regarding our report.

Please inform us in writing within twenty days of the date of this meeting, of those actions that you have taken or will take to improve performance in the above area of weakness. Additionally, you may also include any comments you may have regarding the SALP report.

Following our meeting and receipt of your response, the enclosed report, your response, and a summary of our findings and planned actions will be placed in the NRC Public Document Room, subject to your review and the procedures of 10 CFR 2.790.

Your cooperation is appreciated.

Sincerely,

Richard W. Starostecki, SALP Board Chairman Director, Division of Project and Resident Programs

Long Island Lighting Company

Enclosure: SALP Report

· . . · .

cc w/encl: J. L. Smith, Manager of Special Projects