RC Form 591			U.S. NUCLEAR REGULATORY COMMISSION
2-81) DCFR 2.201	SAFETY	NEPECTION	
Mobile Cardiovascular Testins 1218 Kilbourne Avenue Milwankee, WI 53233		2. REGIONAL OFFICE U.S. NUCLEAR REGULATORY COMMISSION REGION 111 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137	
DOCKET NUMBER(S)	4. LICENSE NUMBER		
030-28875	48-24	566-01	25 October 1990
egulatory Commissions (NRC) rules and regulatory Commissions (NRC) rules and regulad representative records, interviews, with per 1. Within the scope of this inspection, no v	ations and the conditions of yo sonnel, and observations by th iolations were observed. have taken to correct the viola	our license. The inspect e inspector. The finding stions identified during t	the last inspection. We have no further questions on
THIS IS A NOTICE OF VIOLATION W	hich is required to be posted in	accordance with 10 CF	
C		License	of sealed sources were not performed at the prop Condition Number
D. Records of			were not properly naintaine
E. Documents were not properly poster			Number
F. Reports or notifications of			were not made in accordan
with 10 CFR		or License Condition	Number
L			
9011190260 901 REG3 LIC30 48-24566-01	PDC		
his statement of corrective actions is made in he NRC.	accordance with the requirem	ante of 10 CFR 2.201. P	to the violations identified in the items checked above to further response will be submitted unless required Advances 103119 DEC NECONSPECTOR
SIGNATURE - LICENSEE	DATE	SIGNAT	URE - NRC INSPECTOR DATE