

August 4, 1982

In reply, please
refer to LAC-8465

DOCKET NO. 50-409

Director of Nuclear Reactor Regulation
ATTN: Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch #5
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
SEP TOPIC EVALUATION FOR VI-2.D - MASS AND
ENERGY RELEASE FOR POSSIBLE PIPE BREAK
INSIDE CONTAINMENT; AND VI-3 - CONTAINMENT
PRESSURE AND HEAT REMOVAL CAPABILITY

Reference: (1) NRC Letter, Crutchfield to Linder,
dated July 13, 1982.

Gentlemen:

DPC has reviewed the draft evaluation for LACBWR for the topics
transmitted in Reference (1). This evaluation accurately reflects
the as-built condition of the plant with two corrections required.

The corrections are:

- 1) Page 4 of SER -
1st full paragraph,
Sentence 6: ".....and/or the Manual
Depressurization System."
- 2) Page 5 of Appendix A,
Item 4, Sentence 2: "Scram would normally occur in
approximately one second due to
the MSIV closure on a low steam
line pressure or a low reactor
water."

A035


Mr. Dennis M. Crutchfield, Chief
Operating Reactors Branch #5

LAC-8465
August 4, 1982

If you have any further questions, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE



Frank Linder, General Manager

FL:RMB:af

cc: J. G. Keppler, Reg. Adm., NRC-DRO III
NRC Resident Inspector