. ... DAIRYLAND POWER COOPERATIVE La Crosse, Wisconsin 54601 November 30, 1978 In reply, please refer to LAC-6020 DOCKET NO. 50-409 Mr. James G. Keppler Regional Director U. S. Nuclear Regulatory Commission Directorate of Regulatory Operations Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137 SUBJECT: DAIRYLAND POWER COOPERATIVE LA CROSSE BOILING WATER REACTOR (LACBUR) PROVISIONAL OPERATING LICENSE NO. DPR-45 REPORTABLE OCCURRENCE NO. 78-08 (REVISED) Reference: (1) DPC Letter, Madgett to Keppler, LAC-5381, dated July 17, 1978. Dear Mr. Keppler: Reference (1) provided notification of a Reportable Occurrence related to the operable status of one zone of the fire detection system. This letter forwards a revised Licensee Event Report which clarifies the cause of the Reportable Occurrence. If there are any questions concerning these changes, please contact us. Very truly yours, DAIRYLAND POWER COOPERATIVE Frank Linder, General Manager FL: JDP: af Attachment cc: (See Attached) - 1 -7/110110165

Mr. James G. Keppler Regional Director

LAC-6020 November 30, 1978

CC: Director, Office of Inspection and Enforcement (30)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Director, Office of Management Information and (3)
Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555