



WZ-QAN-82-019

June 17, 1982

United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

ATTN: Glen D. Brown, Chief
Technical Program Branch

RE: License 43-18296-01

Dear Mr. Brown:

In response to your letter dated June 8, 1982 regarding the corrective steps to be taken to avoid further violations found during your audit, the following steps will be implemented:

- (a) Closer scrutiny paid to document identification and compatibility of source material and storage camera.
- (b) Westinghouse corporate headquarters is issuing an outline to all radiation facilities in order to produce more uniform internal control of operational procedures.
- (c) All quarterly reports (forms RE-1 thru RE-7) and calibrations will be reviewed not only by the Radiation Safety Officer, but by the manager of the Non-Destructive Testing area.
- (d) Westinghouse corporate headquarters is sending the manager of radiological materials and administrative control to audit the radiographic facility in order to better control our operations in compliance with NRC regulations.

Sincerely yours,

A handwritten signature in cursive script that reads 'R. A. White'.

R. A. White, Manager
NDT and Inspection

RAW/idt

8208120065 820722
NMS LIC30
43-18296-01 PDR
3200A

