



PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4502

JOHN S. KEMPER
VICE PRESIDENT
ENGINEERING AND RESEARCH

JUL 19 1982

Mr. Ronald C. Haynes, Director
United States Nuclear Regulatory Commission
Office of Inspection and Enforcement, Region I
631 Park Avenue
King of Prussia, PA 19406

Subject: US NRC IE Region I Letter dated February 4, 1982
RE: Site Inspection of December 1, 1981-January 8, 1982
Inspection Report 50-352/81-17 and 353/81-15
Limerick Generating Station - Units 1 and 2

Reference: Philadelphia Electric Company Letter to the NRC, dated
May 28, 1982

File: QUAL 1-2-2 (352/81-17 and 353/81-15)

Dear Mr. Haynes:

The corrective action forwarded in the referenced response noted that 125 pipe spools supplied by Texas Pipe were to be inspected for minimum wall thickness requirements.

This inspection has been completed and 2 pipe spools were found with minimum wall thickness violations. Hence a 100% inspection of Q-listed spools supplied by Texas Pipe will be performed. The inspection will be completed by December 30, 1982.

Sincerely,

FJC/mmk

Copy to: Director of Inspection and Enforcement
United States Nuclear Regulatory Commission
Washington, D. C. 20555

E. B. McCabe, US NRC

