

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 POOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

NOV 1 4 .378

Docket No. 50-282 Docket No. 50-306

Northern States Power Company
ATTN: Mr. Leo Wachter
Vice President
Power Production and
System Operation
414 Nicollet Mall
Minneapolis, MN 55401

Gentlemen:

This refers to the inspection conducted by Mr. M. D. Riden of this office on October 16-20, 1978, of activities at Prairie Island Nuclear Generating Station, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-42 and No. DPR-60 and to the discussion of our findings with Mr. Tierney at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each *tem of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room, except as follows. If the enclosures contain information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Gaston Fiorelli, Chief Reactor Operations and Nuclear Support Branch

Enclosures:

- 1. Appendix A, Notice of Violation
- IE Inspection Reports No. 50-282/78-14 and No. 50-306/78-15

cc w/encls: Mr. F. P. Tierney, Jr., Plant Manager John W. Ferman, Ph.D. Nuclear Engineer, MPCA Central Files Reproduction Unit NRC 205 PDR Local PDR NSIC TIC