NRC Form 591		***	U.S. NUCLEAR REGULATORY COMMISSION
(12-01) 10 CF# 2:201 *	SAFETY INSP	ECTION	
1 LICENSEE Briggs Associates 400 Hingham Rockland, Moss 023	the second se	475 Al	RC - Reyion I Iendale Ruad Prussia, Pennsylvania 19406
030 - 10963	4. LISENSE NUMBER(S) 20-16401	-01	OCTOBER 25, 1990
those actions at this time 3. During this inspection certain of your activit THIS IS A NOTICE OF VIOLATION which	ns and the conditions of your lig nel, and observations by the inspe ions were observed. In taken to correct the violations i les, as checked below, were in vio is required to be posted in accor	ense. The inspection loctor. The findings a identified during the plation of NRC required clance with 10 CFR	n consisted of selective examinations of procedures as a result of this inspection are as follows: I last inspection. We have no further questions on inaments.
Image: Construction of the presence of radioa Construction Trequencies D. Records of the property posted or of the prop	<u>alenge Certin</u> or Li	License Co te of Cim cense Condition Nur	of sealed sources were not performed at the proper andition Number
F. Reports or notifications of			were not made in accordance
At Type & package	hot properly s	secured fo	er transport 10 (FR71
	llen 10378 901025 1030	Return Or	iginal to Region I IE:07
I hereby wate that within 30 days the actions description of corrective actions is made in according to RC.	ibed by me to the inspector will ordance with the requirements of 10/25/90	De taken to correct 10 CFR 2 201. No Outfor SIGNATUP	the violations identified in the items checked above further response will be submitted unless required by Kinkerson 10/25/90