

# LICENSEE EVENT REPORT

CONTROL BLOCK \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | N | P | I | N | 1 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 14 15 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT LR

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 0 | 2 | 8 | 2 | 7 | 1 | 1 | 3 | 0 | 7 | 8 | 8 | 1 | 2 | 2 | 0 | 7 | 8 | 9

7 8 60 61 66 67 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90

REPORT SOURCE SOCKET NUMBER EVENT DATE REPORT DATE

0 2 | During power operation (and during relay testing at Unit 2 refueling) Safeguards

0 3 | Bus 16 was inadvertently locked out of service for about 2 minutes. Redundant bus

0 4 | was operable. Tech Spec 3.7.A.2 applies. No effect on public health and safety.

0 5 |

0 6 |

0 7 |

0 8 |

0 9 | E | B | A | F | E | L | E | C | O | N | Z | Z

9 10 11 12 13 14 15 16 17 18 19 20 21 22

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

17 | 7 | 8 | 0 | 2 | 3 | 0 | 3 | L | 0

21 22 23 24 25 26 27 28 29 30 31 32

LER NO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO

18 | H | H | Z | Z | 0 | 0 | 0 | 0 | N | N | Z | Z | 9 | 9 | 9 | 9

33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NRC-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

1 0 | An electrical jumper was applied without proper review and approval. Control room

1 1 | annunciation prompted quick corrective action. Retraining in plant administrative

1 2 | controls will be done at future outages.

1 3 |

1 4 |

1 5 | E | 1 | 0 | 0 | N/A | A | Control room annunciation

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | Z | NA | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | Z | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ISSUED DESCRIPTION PUBLICITY

7812260209