



August 5, 1982

Log No. K82-1159
FILE: RR 2 (NP-33-82-37)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 82-032
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: July 4, 1982

Enclosed are three copies of Licensee Event Report 82-032 with supplemental information sheets, which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/lmr
Enclosure

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Walt Rogers
NRC Resident Inspector
Encl: 1 copy

AUG 9 1982

8208130078 820805
PDR ADOCK 05000346
S PDR

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

4322