



Heartland Cancer  
Treatment Center

DCD/DCB

November 6, 1990

Ms. Evelyn Matson  
Radiation Specialist  
United States Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

*License File*  
24-13246-02

Dear Ms. Matson,

This correspondence is in regards to our response to violations which resulted from your inspection on August 22nd, 1990.

During our subsequent telephone conversation on November 5, 1990, you mentioned our failure to:

1. Specify that the beam uniformity test will be done annually, and
2. Set up a mechanism for auditing the corrective measures mentioned in our response to these violations.

Beam uniformity test will be done annually on the Cobalt-60 teletherapy unit during its annual full calibration due in February.

Copies of the violations and our response will be sent to Dr. Edward Stevens, R.S.O. and Chairman of the Radiation Safety Committee. The Radiation Safety Committee will review and audit the corrective measures stated in our response during their quarterly radiation meetings.

Sincerely,

Colville E. Osborne, MSc.  
Physicist

/dak

901 Robidoux Street • St. Joseph, Missouri 64501 • 816-271-7280  
A subsidiary of Heartland Health System

9012030090 901106  
REGS LIC30  
24-13246-02 PDC

*IEO 7*  
|||  
NOV 18 1990