

APPENDIX B

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report: 50-267/90-18 Operating License: DPR-34

Docket: 50-267

Licensee: Public Service Company of Colorado (PSC)
P.O. Box 840
Denver, Colorado 80201-0840

Facility Name: Fort St. Vrain Nuclear Generating Station (FSV)

Inspection At: FSV, Platteville, Colorado

Inspection Conducted: October 22-26, 1990

Inspector: Charles L. Cain for 11/20/90
R. A. Caldwell, Senior Security Inspector Date
Nuclear Materials and Safeguards Inspection
Section

Approved: Charles L. Cain 11/20/90
Charles L. Cain, Chief, Nuclear Materials and Date
Safeguards Inspection Section

Inspection Summary

Inspection Conducted October 22-26, 1990 (Report 50-267/90-18)

Areas Inspected: Routine, unannounced inspection of the licensee's physical security program. The areas inspected within the physical security program included protected and vital area (VA) barriers, detection and assessment aids; protected and VA access control of personnel, packages, and vehicles; communications; and testing, maintenance, and compensatory measures.

Results: Within the program areas inspected, one violation was identified (inadequate detection aids - protected area, paragraph 3).

Immediate corrective action was taken with regard to Violation 267/9018-01, and the root cause of the problem was addressed. The inspector determined that the licensee's corrective action was prompt and adequate; therefore, no response to this violation is required.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

9012060192 901129
PDR ADOCK 05000267
Q PNU

The licensee no longer has new fuel stored on site and is not operating the reactor. The licensee has submitted a 10 CFR 50.59 change to the physical security plan (PSP). This PSP submission is expected to be approved by the Office of Nuclear Reactor Regulation.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED