

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

DEC 17 1993

Docket: 50-458 License: NPF-47

Gulf States Utilities
ATTN: John R. McGaha, Vice President
River Bend Nuclear Group
P.O. Box 220
St. Francisville, Louisiana 70775

SUBJECT: NRC INSPECTION REPORT 50-458/93-27 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Mr. W. F. Smith, and the inspectors identified in the attached report, of this office on September 26 through November 6, 1993. The inspection included a review of activities authorized for your River Bend Station facility. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements.

Based on the results of this inspection, certain licensed activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The first violation is of concern because an appropriate postmaintenance test was not specified after performing an adjustment to a breaker supplying power to a safety-related, motor-operated valve. A similar violation was identified in February 1993, as documented in NRC Inspection Report 50-458/93-05. In your response, please address the reason corrective actions taken in response to that violation did not prevent recurrence. The second violation is of concern because, although the examples cited were of minor consequence, it demonstrated that not all of your staff is complying with your stated expectations to either follow procedures or to stop and have the procedures corrected. We continue to hold the view that working around deficient procedures is unacceptable. The third violation is of concern because deficient inservice testing procedures were identified previously in NRC Inspection Report 50-458/93-05, and you had committed to walk down these procedures prior to use. Your previous actions did not appear to have been effectively implemented, and your response should reinforce the previous commitment by addressing auditional actions that will most likely prevent recurrence.

One unresolved item was identified concerning the cause of a local power range monitor test switch that was discovered incorrectly positioned during a reactor startup. This matter is discussed in Section 2.4 of the enclosed inspection report and will remain open pending the completion of your investigation.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notices when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to the Notices, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC commitments and regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

A. Bill Beach, Director Division of Reactor Projects

Enclosures:

 Appendix A - Notice of Violation
 Appendix B - NRC Inspection Report 50-458/93-27

cc w/enclosures: Gulf States Utilities ATTN: J. E. Booker, Technical Assistant P.O. Box 220 St. Francisville, Louisiana 70775 Gulf States Utilities
ATTN: Harold W. Keiser, Senior Vice
President
P.O. Box 220
St. Francisville, Louisiana 70775

Gulf States Utilities ATTN: Michael B. Sellman, Plant Manager P.O. Box 220 St. Francisville, Louisiana 70775

Gulf States Utilities
ATTN: James J. Fisicaro, Manager - Safety
Assessment and Quality Verification
P.O. Box 220
St. Francisville, Louisiana 70775

Winston & Strawn ATTN: Mark J. Wetterhahn, Esq. 1401 L Street, N.W. Washington, D.C. 20005-3502

Gulf States Utilities
AYTN: Les England, Director
Nuclear Licensing
P.O. Box 220
St. Francisville, Louisiana 70775

Mr. J. David McNeill, III William G. Davis, Esq. Department of Justice Attorney General's Office P.O. Box 94095 Baton Rouge, Louisiana 70804-9095

H. Anne Plettinger 3456 Villa Rose Drive Baton Rouge, Louisiana 70806

President of West Feliciana Police Jury P.O. Box 1921 St. Francisville, Louisiana 70775

Cajun Electric Power Coop. Inc. ATTN: Philip G. Harris 10719 Airline Highway P.O. Box 15540 Baton Rouge, Louisiana 70895 Hall Bohlinger, Administrator Radiation Protection Division P.O. Box 82135 Baton Rouge, Louisiana 70884-2135 bcc to DMB (IEO1)

bcc distrib. by RIV:

J. L. Milhoan Section Chief (DRP/C) MIS System RIV File Senior Resident Inspector, Cooper A. B. Beach, D/DRP

Resident Inspector Lisa Shea, RM/ALF, MS: MNBB 4503 DRSS-FIPS Section Chief (DRP/TSS)

RIV:SRI*	DRP/C*	C:DRP/C*	D: PRP	
WFSmith;df	EECollins .	JEGagliardo	ABBeach	
12/7/93	12/7/93	12/7/93	12/17/93	

^{*}Previously concurred

bcc to DMB (IEO1)

bcc distrib. by RIV:

J. L. Milhoan Section Chief (DRP/C) MIS System RIV File RIV File Section Chief (DRP/TSS)
Senior Resident Inspector, Cooper A. B. Beach, D/DRP

Resident Inspector Lisa Shea, RM/ALF, MS: MNBB 4503 DRSS-FIPS

RIV:SRI*	DRP/C*	C:DRP/C*	D:DRP	
WFSmith;df	EECollins	JEGagliardo	ABBeach	
12/7/93	12/7/93	12/7/93	12/17/93	- 7.