



Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

August 10, 1982

Mr. James G. Keppler, Regional Administrator
 Directorate of Inspection and
 Enforcement - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

orig + 1

PRINCIPAL STAFF			
✓ RA	<i>kas</i>	DM	
D/RA		EMF	
S/RA		RP	
✓ GRANT		RAO	
DEPELOS		SLO	
GESTP			
HL			
OL		FILE	<i>kas</i>

Subject: LaSalle County Station Unit 1
 Structural Bolting Tightness
 Inspection Program for Reactor
 Containment Valves
NRC Docket No. 50-373

Reference (a): Amendment 3 to License NPF-11
 dated July 15, 1982, Item 2.C.(31).

Dear Mr. Keppler:

The Structural Bolting Tightness Inspection program has been completed for containment valves. The results of this inspection program are contained in the following attachments:

- Summary of inspection results - 2 pages
- Engineering evaluation of the inspection results - 1 page
- Inspection data sheets - 48 pages
- Inspection program description - 8 pages

A copy of this information was given to NRC Region III Inspector Roger Lanksbury, during his July 17, 1982 on-site review of the inspection results. As a result of his review, some additional data was obtained and additional information was added on some of the data sheets to clarify existing inspection data.

A total of 2,600 bolts essential to the operation of the valves were inspected. Of these 2,600, 5 bolts were found to have tightness discrepancies. These discrepancies were reviewed by CECO Project Engineering and determined not to be safety significant. Therefore, a nonconformance report was not initiated.

The inspection program for valves outside containment is being developed. The inspection work will be completed before January 15, 1983 in accordance with the requirements in Reference (a).

8208170223 820810
 PDR ADOCK 05000373
 Q PDR

AUG 12 1982

DE 34

J. G. Keppler

- 2 -

August 10, 1982

We had previously agreed to transmit to Region III a report of our inspection activities. The enclosed information fulfills our commitment for those valves inside containment.

If you have any further questions in this matter, please contact this office.

Very truly yours,

CW Schroeder 8/10/82

C. W. Schroeder
Nuclear Licensing Administrator

lm

Attachment

cc: NRC Resident Inspector - LSCS

4718N