


Bar Disease Mee Prenigent



Trojan Nuclear Plant Docket 50-344 License NPF-1

Mr. R. H. Engelken, Director
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 N. California Blvd.
Walnut Creek, CA 94596

Dear Mr. Engelken:

This is in response to IE Bulletin 80-21 of November 6, 1980, concerning valve yokes supplied by Malcolm Foundry Company, Inc.

All valve manufacturers supplying safety-related valves for the Trojan Nuclear Plant were contacted concerning their use of valve parts cast by Malcolm Foundry Company, Inc. All manufacturers, except Anchor-Darling, confirmed they had never purchased any cast valve parts from Malcolm Foundry Company, Inc. Anchor-Darling has confirmed that the only valve parts they purchased from Malcolm Foundry Company, Inc. were purchased by their New Jersey facility, whereas valves in use at the Trojan Nuclear Plant originated from their Hayward, California facility.

Therefore, no further investigation is warranted as outlined in the bulletin.

Sincerely,

Bart D. Withers Vice President

Nuclear

c: Mr. Lynn Frank, Director State of Oregon Department of Energy

Director
Division of Reactor
Construction Inspection
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission

121 S.W. Salmon Street, Portland, Oregon 97204

POOR ORIGINAL

80-323