FORM NRC-591 (3-77)

## U.S. NUCLEAR REGULATORY COMMISSION ATED ORIGINAL

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

1. LICENSEE	AND ANT OF IS REGIONAL OFFICE
Harrington Memo	Office of Inspection & Enforcement  Region I
Southbridge, Mas	631 Park Avenue
3. DOCKET NUMBER(S)	King of Prussia, Pa. 19406
30-08187	20-14868-01 July 20,1982
6. INSPECTION FINDINGS	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:	
No items of noncompliance or unsa	fe conditions were found.
The following items of noncompliance related to records, signs, and labels were found:	
A. Rooms or areas were not proper	ly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42
B. Rooms or areas were not proper 10 CFR 20.203(c) (1) or 34.42	ly posted to indicate the presence of a HIGH RADIATION AREA.
C. Rooms or areas were not proper 10 CFR 20.203(d)	ly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA.
D. Rooms or areas were not proper	ly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)
E. Containers were not properly lat 10 CFR 20.203(f) (1) or (f) (2)	beled to indicate the presence of RADIOACTIVE MATERIAL.
F. A current copy of 10 CFR 20, a made available, 10 CFR 20.2060	copy of the license, or a copy of the operating procedures was not properly posted or b)
☐ G. FormNRC-3 was not properly p	osted. 10 CFR 20.206(c)
H. Records of the radiation exposu	re of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)
Records of surveys or disposals v	were not properly maintained. 10 CFR 20.401(b) or 34.43(d)
J. Records of receipt, transfer, disp 10 CFR 30.51, 40.61 or 70.51	posal, export or inventory of licensed material were not properly maintained.
☐ K. Records of leak tests were not m	naintained as prescribed in your license, or 10 CFR 34.25(c)
L. Records of inventories were not	maintained. 10 CFR 34.26
M. Utilization logs were not mainta	ined. 10 CFR 34.27
N. Records of radiation survey inst	rument calibration were not maintained. 10 CFR 34.24
	l interlock tests were not maintained as prescribed in your license.
P. Other president	wered constance found in 790/
7. The NRC Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.	
8208180107 820720 NMS LIC30 20-14868-01 PDR	IE07
(Date)	(Licensee Representative - Title or Position)