


**LICENSEE EVENT REPORT**

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1			J	S	G	S	2	(2)	o	o	-	o	o	o	o	o	-	o	o	(3)	4	1	1	1	1	(4)			(5)		
7	8							14	15											25	26							57	CAT	58		
				LICENSEE CODE					LICENSE NUMBER																	LICENSE TYPE						

CON'T

0 1  
 7 8  
 REPORT SOURCE L 6 0 5 0 0 0 3 1 1 7 0 7 1 5 8 2 8 0 8 0 4 8 2 9  
 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On July 15, 1982, during a review of Unit 2 surveillance testing it was noted that

0 3 | Surveillance Requirement 4.7.10.2.b had not been fulfilled. Surveillance 4.7.10.2.b

0 4 | requires cycling of each testable automatic valve in the Fire Suppression System every

0 5 | 12 months, and is normally accomplished by performing Appendix P of the Fire Fighting

0 6 | Manual. The surveillance was overdue as of April 19, 1982 and Action Statement

0 7 | 3.7.10.2.a was entered retroactive to that time. The Fire Protection Supervisor

0 8 | immediately performed Appendix P. The systems tested satisfactorily on July 15, 1982,

7 8 9 | as they had during the previous performance of Appendix P on January 16, 1981. 80

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP SUBCODE		VALVE SUBCODE			
0	9	A	B	A	F	Z	Z	Z	Z	Z	Z	Z	Z	Z			
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17	8	2	—	0	6	2	/	0	3	L	—	0					
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
X	Z	Z	Z	Z	Z	0	0	0	0	Y	N	N	Z	Z	9	9	9
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 In anticipation of a new procedure, the Computer Inspection Order (IO) cards for  
1 1 Appendix P were prematurely cancelled. Because the new procedure was not issued and  
1 2 no notice from the IO System was sent, the surveillance was missed. Appendix P was  
1 3 performed, fulfilling the surveillance, and Action Statement 3.7.10.2.a was  
1 4 terminated on July 15, 1982. New IO cards were issued and the implications of this  
7 8 9 occurrence were discussed with the personnel involved.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) E % POWER (29) 0 8 2 OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B DISCOVERY DESCRIPTION (32) Routine Inspection

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) NA 44

7 8 9 10 11 45 84

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	0 0 0 (37) 2 (38)	NA (39)

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	40	NA

8 9		11 12		80	
TYPE		LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION	
1	9	Z	42	43	NA

8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45) 8208190144 820804  
2 0 N (44) NA PDR ADDCK 05000311  
S PDR NRC USE ONLY

NRC USE ONLY

NAME OF PREPARER

R. Heller

PHONE: (609) 541-5900 629