1750 Chestnut Street Tower II

January 28, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE REPORT BFRO-50-260/8104

The enclosed report provides details concerning reactor water level switches LIS-3-203A switch 1, LIS-3-A, B, C, and D switches 2 which were found outside of technical specification limits. This report is submitted in accordance with Browns Ferry unit 2 Technical Specification 6.7.2.A(1).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green Director of Nuclear Power

Enclosure (3) cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavalice Nuclear Safety Analysis Center Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

A002

8102040514

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES