

## LICENSEE EVENT REPORT

**EXHIBIT A**

CONTROL CLOCK | | | | | | | |

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 LCL AIR sisli 0101-10101010101010141111110110  
2 3 4 LICENSE CODE 14 15 16 LICENSE NUMBER 17 18 19 20 21 22 23 24 25 26 27 28 29 30

CONT

REPORT SOURCE [L15!015!010!013!11!2!3!011!1!2!8!1!5!012!015!8!1!5]  
C 61 CUSTID 50 62 EVENTDATE 74 75 REPORTDATE 62

**EVENT DESCRIPTION AND PREDICTABLE CONSEQUENCES (10)**

- [61] In J-52-81, a CCW system sample showed a H<sub>3</sub> level greater than MDA. A Back-up sample verified that some low-level activity was, in fact, present in the CCW System. Per IE Bulletin 80-10, a safety evaluation was performed. The safety evaluation determined that the operation of the system did not constitute an unreviewed safety question nor require a Technical Specification change. Continued operation was in compliance with all applicable regulations, commitments and the Technical Specifications.

05	SYSTEM CODE	W B (11)	CAUSE CODE	E (12)	CAUSE SUBCODE	B (13)	COMPONENT EDGE	H T E X I C H (14)	COMP. SUBCODE	C I (15)	VALVE SLECODE	Z (16)
2 8	9 10	11	12	13	14	15	16	17	18	19	20	
(17) EFR- REPORT NUMBER	EVENT-YEAR	81			SEQUENTIAL, REPORT NO.	0 1 0 2		OCCURRENCE CODE	0 1 3	REPORT TYPE	L	REVISION NO
21 22	23	24	25	26 27	28	29	30	31	32	33	34	
ACTION TAKEN	FUTURE ACTION	DISPLAY	SHUTDOWN METHOD	TIME	ATTACHMENT SUBMITTED	APPROV. FORMS	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER				
X (38)	F (39)	Z (40)	Z (41)	0 1 0 1 0 1 0 (42)	Y (43)	Y (44)	N (45)	G 1 2 1 1 0 (46)				
33 34	35	36	37	38	39	40	41	42	43	44	45	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (47)												

- 10 A leak search program determined that the "A" Letdown Cooler, E-220A, was  
11 the source of the contamination. The "A" Cooler will be isolated during  
12 Cycle 5 operations except during specific periods when increased cooling  
13 capacity is required. Operation will be in compliance with all applicable  
14 regulations, commitments and the Technical Specifications.

FACILITY STATUS		N POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	1	0	1	0	1	0	1	Routine Surveillance
7	8	9	10	11	12	13	14	15	
ACTIVITY CONTENT				AMOUNT OF ACTIVITY				LOCATION OF RELEASE	
1	6	1	7	1	8	1	9	1	N/A
2	3	4	5	10	11	12	13	14	
PERSONNEL EXPOSURES									
NUMBER				DESCRIPTION					
1	7	1	0	1	0	1	0	1	N/A
2	3	4	5	11	12	13	14	15	
PERSONNEL INJURIES									
NUMBER				DESCRIPTION					
1	5	1	0	1	0	1	0	1	N/A
2	4	3	5	11	12	13	14	15	
LOSS OF OR DAMAGE TO FACILITY									
TYPE									
1	5	1	0	1	0	1	0	1	N/A
2	3	4	5	11	12	13	14	15	
PUBLICITY									
MEDIA				DESCRIPTION					
1	0	1	0	1	0	1	0	1	NRC USE ONLY
2	3	4	5	11	12	13	14	15	
Local newspapers and wire service									

第六章 計算機的運算能力

NOC USE ONLY

24

Monterey (916) 452-3211

8192170

NAME OF RECIPIENT - R. W. Colombo

PHONE (916) 452-3211