## TENNESSEE VALLEY AUTHORITY

CHATTANOOGA TENNESSEE 37401 1750 Chestnut Street Tower II

August 10, 1982

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE REPORT BFR0-50-259/82013 R1

This report is a supplement to my letter to you dated February 12, 1982 concerning degraded voltage relays whose trip setpoint was found to be below the minimum allowable trip point setting. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.a(9).

Very truly yours,


TENNESSEE VALLEY AUTHORITY


J. Green Director of Nuclear Power

Enclosure cc (Enclosure): Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

> Records Center Institute of Nuclear Power Operations 1820 Water Place Atlanta, Georgia 30339

NRC Inspector, Browns Ferry





An Equal Opportunity Employer