needen sterste werden die der beiter verschieden der einen der einen sterken eine sterste einen der sterste ver		OWBCIE-0D
NRC FORM 591 PART 1 (7-91)		U.S. NUCLEAR REGULATORY COMMISSIO
10 CFR 2.201	SAFETY INSPI	ECTION
		Page 1 of _/
1. LICENSEE	2. REGIO	INAL OFFICE
		REGION IV
Glenrock Goal Co- 1026 - 55 Ranch Ro	ad /	U S NUCLEAR REGULATORY COMMISSION
		611 RYAN PLAZA DRIVE SUITE 400 ARLINGTON TX 76011-8064
Glencost, Wysoming	88027	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION
030-22233	49-23470-01	November 30, 1993
procedures and representative records, interv ollows: 1. Within the scope of this inspection,	no violations were observed. s you have taken to correct the viola	cense. The inspection consisted of selective examinations of ns by the inspector. The findings as a result of this inspection are in tions identified during the last inspection. We have no further
	ur activities, as described below or a equired to be posted in accordance	ttached, were in violation of NRC requirements. This form is a with 10 CFR 19.11. was not properly posted to . 10 CFR 20.203(b),(c),(d),(e) or 34.42
В.		of sealed sources were not
performed at the proper freq	uencies, 10 CFR	or License Condition Number
C. Records of		were not properly maintained.
10 CFR	or License Condition Number	
D. Documents were not properly	y posted or otherwise made availabl	e. 10 CFR 19.11.
E Deporte or patification of		were not made in an advantage with
10 CFR	or License Condition Number	the second s
F	an any sea burnes to be an any season of the se	
		will be taken to correct the violations identified in the items checked rements of 10 CFR 2.201. No further response will be submitted
SIGNATURE - LICENSEE	DATE SIGNATI	JRE NRC INSPECTOR // DATE //
NUMBER - LIGENOEE	SIGNAT	JRE - NRC INSPECTOR DATE