Babcock & Wilcox

a McDermott company

Nuclear Power Generation Divisic."

3315 Old Forest Road P.O. Box 1260 Lynchburg, Virginia 24505-1260 (804) 385-2000

December 2, 1981

Mr. John S. Berggren
Standardization and Special Projects Branch
U. S. Nuclear Regulatory Commission
7920 Norfolk Avenue
Bethesda, MD 20814



Dear Mr. Berggren:

Enclosed are 35 copies of Topical Report BAW-10151A, "Control Rod Guide Tube Wear Measurement Program," the accepted version of a report formerly denoted as BAW-1623. Included in the report are your Safety Evaluation Report and acceptance letter. No other changes have been made to the body of the report.

We have changed the number designation of this report to conform to our numbering system for Topicals but have left reference to the previous designation, BAW-1623, on the cover and title page so as not to cause undue filing problems.

We understand that this report is now acceptable for referencing by B&W 177-FA plants licensees.

Very truly yours J. H. Taylor

Manager, Licensing

TOID

cc R. B. Borsum

12170166 811202 DR TOPRP EMURI PDR