

30-02016

AUG 16 1982

Mercy Hospital  
ATTN: Mr. Robert Esker  
Vice President Professional  
Support and Services  
Departments of Radiology and  
Clinical Laboratory  
Muskegon, Michigan 49443

License No. 21-02187-01

Gentlemen:

This refers to the routine safety inspection conducted by P. J. Whiston of this office on August 4, 1982, of activities authorized by NRC Byproduct Material License No. 21-02187-01 and to the discussion of our findings with you and Mr. W. Erickson, CNMT at the conclusion of the inspection.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated July 16, 1979, regarding apparent items of noncompliance found during our April 17, 1979, inspection. We have no further questions regarding these matters.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2

cc: Mr. A. E. DeMers, Director  
of Radiological Services  
DMB/Document Control Desk (RIDS)

RIII

RIII

Whiston/sv  
8/13/82

Sreniawski

IE HQ FILE COPY

8208200092 820816  
NMS LIC30  
21-02187-01 PDR

DMB IE-07