

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | A | R | I | S | S | 1 | 2 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 3 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

0 1 | L | 5 | 0 | 8 | 0 | 0 | 0 | 3 | 1 | 2 | 7 | 0 | 7 | 1 | 4 | 8 | 2 | 3 | 0 | 8 | 1 | 6 | 8 | 2 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a routine snubber surveillance inspection, one snubber was found
0 3 | to fail its acceptance criteria: Snubber ISW-23823-7A failed its visual
0 4 | inspection due to low fluid level. There were no transients associated
0 5 | with this event since the unit was in cold shutdown during the inspection
0 6 | nor was the outage extended due to this event. Plant and public
0 7 | safety were not affected.

0 9 | C | U | 11 | E | 12 | B | 13 | S | U | P | O | R | T | 14 | D | 15 | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | 0 | 1 | 8 | 23 | 24 | 26 | 0 | 3 | 27 | 28 | 29 | L | 30 | 31 | 0 | 32
EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
18 | B | 19 | X | 20 | Z | 21 | Z | 22 | 0 | 0 | 0 | 0 | 23 | Y | 24 | Y | 25 | N | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Snubber ISW-23823-7A was rebuilt and passed its functional test.
1 1 | Snubber surveillance interval is now set at twelve months.

1 5 | G | 28 | 0 | 0 | 0 | 29 | N/A | 30 | B | 31 | Snubber inspection | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

1 6 | Z | 33 | Z | 34 | N/A | 35 | N/A | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1 7 | 0 | 0 | 0 | 37 | Z | 38 | N/A | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 | 0 | 0 | 40 | N/A | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | N/A | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | Y | 44 | Local newspapers and wire services. | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34
PUBLICITY ISSUED DESCRIPTION NRC USE ONLY

NAME OF PREPARER: R. W. Colombo PHONE: (916) 452-3211