Appendix

## NOTICE OF VIOLATION

River Cement Company

License No. 24-10263-03

As a result of the inspection conducted on July 26, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition 13A(1) states that each sealed source containing licensed material, other than Hydrogen 3, with a half-life greater than thirty days and in any form other than gas shall be tested for leakage and/or contamination at intervals not to exceed 6 months.

Contrary to this requirement, the cesium-137 sealed sources used in your gauges were not tested for leakage and/or contamination every 6 months. The last leak test for most of your sealed sources was on June 19, 1980. The last leak test for the sealed source used in gauge, DH2LL (located on the south side of No. 2 kiln dust surge bin) was on December 7, 1978.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Datad

D. G. Wiedeman, Chief

Materials Radiation Protection

Section 1