## DEC 1 1 1981

License No. 22-01914-02

United Hospital, Inc. ATTN: John B. Marta, M.D. Chairman, Radiation Safety Committee 333 North Smith Avenue St. Paul, MN 55102

## Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on December 2, 1981, of activities authorized by NRC Byproduct Material License No. 22-01914-02 and to the discussion of our findings with you and James Drummond, Administrative Manager, at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as the, relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix. With respect to item 1, the inspection showed that action had been taken to correct the identified noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required and we have no further questions regarding this matter at this time.

Regarding the remaining items, a written response is required.

We will gladly discuss any questions you have concerning this inspection.

Sincerely

D. G. Wiedeman, Acting Chief Materials Radiation Protection

Section 1

Enclosure: Appendix,

Notice of Violation

cc w/encl: Mr. William Casey Assistant Vice President DMB/Document Control Desk (RIDS)

NMS LIC30 22-01914-02

Wiedeman

Burgin jp

12/10/81 8112180428 811211

PDR

IEHQFILE COPY