

DEC 10 1981

Dosimeter Corporation of America
ATTN: Melvin Srybnik
President
Post Office Box 42377
Cincinnati, OH 45242

License No. 34-13477-01
License No. 34-13477-02G
License No. 34-13477-03E

Gentlemen:

This refers to the routine safety inspection conducted by Mr. D. R. Gibbons of this office on November 19, 1981, of activities authorized by NRC Byproduct Material Licenses No. 34-13477-01, No. 34-13477-02G and No. 34-13477-03E and to the discussion of our findings with Mr. Thomas Jackson and Mr. William Connell at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.


No items of noncompliance with NRC requirements were identified during the course of this inspection.

In addition to the above areas, the inspector examined actions described in your letter dated November 8, 1979, regarding apparent items of noncompliance found during our September 17, 1979 inspection of License No. 34-13477-01. We have no further questions regarding these matters.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2



cc: DMB/Document Control Desk (RIDS)

RIII *D/S for*
Gibbons/jr
12/2/81

RIII *D/S for*
Wiedeman
(original signed
by Wiedeman)

RIII *D/S*
Sreniawski
12/10/81

IE07
3
1/D

8112180469 811210
NMS LIC30
34-13477-01 PDR

IE07