

80-555
#8



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

NOV 27 1979

NOTE TO: T. Telford
FROM: W. Kane
SUBJECT: IMPLEMENTATION OF LESSONS LEARNED ITEMS RELATED TO
INADEQUATE CORE COOLING

The B&O Task Force has requested and, in some cases, received information related to short-term Lessons Learned item 2.1.3b (part 1) and 2.1.9 related to inadequate core cooling. In discussions with the various owners groups it appears that two different interpretations exist as to when the ICC procedures are to be in place. We were informed by the W Owners' Group that they are working to a 1/01/80 completion date while The C-E and B&W Owners' Group appear to be working to a 1/31/80 completion date.

Table B-2 of NUREG-0578 states that activity 2.1.9 is to be completed by January 1980. In future discussions with owners groups we plan to advise them that this activity, in conjunction with item 2.1.3b (part 1) must be completed by 1/31/80.

W. F. Kane, Acting Leader
Projects Group
Bulletins & Orders Task Force

cc:
D. Ross
D. Eisenhut
G. Holahan
T. Novak
S. Israel
Z. Rosztoczy
B. Capra
P. O'Reilly
C. Thomas
I. Villalva
G. Kuzmycz

8203010246 810804
PDR FOIA
MADDEN80-555 PDR