

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	J	A	F	1	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
		LICENSEE CODE						LICENSE NUMBER						LICENSE TYPE					CAT	58							

0	1	R	L	6	0	5	0	0	0	3	3	3	7	0	7	0	6	8	3	0	8	0	6	8	2	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	
		REPORT SOURCE		DOCKET NUMBER									EVENT DATE			REPORT DATE										

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 Reserve power breaker 10022 was open for approximately 4 minutes thus causing
 0 3 #3 light house hill line to be not available. No significant hazard existed because
 0 4 the other 115KV Line was still available and is cross tied such that in the event of
 0 5 a unit trip with resulting loss of "house service" power, all loads would have remained
 0 6 energized via the available 115KV line.
 0 7 (Technical Specification Reference: Paragraph 3.9.A.1.a)

0	5	7	8	9
---	---	---	---	---

0	9	E	A	C	Z	Z	Z	Z	Z	Z	Z	Z	Z
7	8	9	10	11	12	13	14	15	16	17	18	19	20
		SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE						COMP. SUBCODE	VALVE SUBCODE

17	8	2	-	0	3	3	/	0	3	L	-	0
21	22	23	24	25	26	27	28	29	30	31	32	
LER RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		

X	H	Z	Z	0	0	0	0	N	N	Z	2	9	9	9	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPR-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Lightning struck one of the two 115KV reserve power lines causing supply breaker to
 1 1 open. The Operator placed the breaker control switch in "Auto After Stop" position
 1 2 negating the auto reclose feature of the breaker while he called power control center
 1 3 and ensured the line was clear for reclosing breaker. No corrective action required.

1	5	7	8	9
---	---	---	---	---

1	5	C	1	0	0	NA	A	Operator observation		
7	8	9	10	11	12	13	14	15		
FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	

1	6	Z	7	NA	NA		
7	8	9	10	11	12		
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	

1	7	0	0	0	Z	NA
7	8	9	10	11	12	13
PERSONNEL EXPOSURES			DESCRIPTION			

1	8	0	0	0	NA
7	8	9	10	11	12
PERSONNEL INJURIES			DESCRIPTION		

1	9	Z	NA
7	8	9	10
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION	

2	0	N	NA
7	8	9	10
PUBLICITY ISSUED		DESCRIPTION	

NRC USE ONLY

8208230363 820809
PDR ADOCK 05000333
S PDR

W. Verne Childs /R.J.Converse

PHONE 315-342-3840