

nm

RECEIVED  
NRC

1982 AUG -9 PM 12: 21

SCE

**Southern California Edison Company**

P. O. BOX 800  
2244 WALNUT GROVE AVENUE  
ROSEMEAD CALIFORNIA 91770

REGION V

TELEPHONE  
(213) 572-1742

J. G. HAYNES  
MANAGER OF NUCLEAR OPERATIONS

August 5, 1982

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: R. H. Engelken, Director

Gentlemen:

Subject: Docket No. 50-206  
IE Bulletin No. 82-02: Degradation of  
Threaded Fasteners in the Reactor Coolant  
Pressure Boundary of PWR Power Plants  
San Onofre Nuclear Generating Station  
Unit No. 1

IE Bulletin No. 82-02 requires the performance of five action items intended to monitor and prevent threaded fastener degradation on the reactor coolant pressure boundary. Action Item No. 5 requests that we provide a report of information identified as a result of Action Item No. 3.


The purpose of this letter is to advise you that we require until October 1, 1982 to comply with Action Item No. 5. This additional time is necessary because Action Item No. 3 requires a review of operating records covering the fifteen years of San Onofre Unit 1 operation. Action Item Nos. 1, 2 and 4 will conform to the schedule specified in IE Bulletin No. 82-02.

If you have any questions, or require further information concerning this subject, please contact me.

Subscribed on this 5 day of August, 1982.

Very truly yours,

By J. G. Haynes  
J. G. Haynes  
Manager of Nuclear Operations



Subscribed and sworn to before me  
this 5th day of August, 1982

Agnes Crabtree  
Notary Public in and for the County  
of Los Angeles, State of California

1E11

8208230368 820805  
PDR ADOCK 05000206  
PDR

82-316