

ENCLOSURE 1

NOTICE OF VIOLATION

Department of the Navy
Washington, DC

Docket No. 030-29462
License No. 45-23645-01NA

During an NRC inspection conducted on October 28-29 and December 3, 1993, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violation is listed below:

Condition 18 to NRC License No. 45-23645-01NA requires, in part, that the licensee adhere to the provisions of the license application (the application) dated August 14, 1986.

Item 10.d of the application states, in part, that the Naval Radiation Safety Committee (NRSC) may issue permits of broadscope to Navy commands authorizing the command's Radiation Safety Committee certain internal prerogatives, such as designating users of licensed material, consistent with the provisions of 10 CFR 33.13.

The NRSC issued Navy Radioactive Materials Permit No. 19-64223-41NP to the Naval Medical Research Institute (NMRI) authorizing the NMRI Radiation Safety Committee to designate authorized users of NRC licensed byproduct material.

Contrary to the above, on October 6 and 7, 1993, NRC licensed byproduct material was used in Room 220 of the Naval Medical Research Institute Annex, Rockville, Maryland by a person who had not been authorized to use byproduct material by the NMRI Radiation Safety Committee under the authority delegated to it by the NRSC.

This is a Severity Level IV violation (Supplement VI).

Dated at Atlanta, Georgia
This 6th day of January 1994