(7-91) 10 CFR 2.201

SAFETY INSPECTION

Page 1 of

1 LICENSEE Tennessee Valley Authority Senior Vice President, Nuclear Power 1101 Market Street, LP 6N 38A-C Chattanooga, Tennessee 37402-2801		2. REGIONAL OFFICE REGION II U.S. NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(5. DATE OF INSPECTION
030-09944 41-08165-0			12/14/93
Regulatory Commission (NRC) rules and regulatory	lations and the condition	is of your license. The	ate to radiation safety and to compliance with the Nuclear inspection consisted of selective examinations of spector. The findings as a result of this inspection are as
Within the scope of this inspection.	no violations were observ	ved.	
questions on those actions at this ti	me. ur activities, as described	below or attached, wer	ed during the last inspection. We have no further te in violation of NRC requirements. This form is a
NOTICE OF VICENTIAN, WITH IS IN	dolled to be bosted in at	cordance with 10 Grin	
A			was not properly posted to
indicate the presence of a			10 CFR 20.203(b),(c),(d),(e) or 34.42.
В			of sealed sources were not
performed at the proper frequ	uencies. 10 CFR	or Licer	nse Condition Number
C. Records of			were not properly maintained.
10 CFR	or License Condition I	Number	
D. Documents were not properly	posted or otherwise ma	de available. 10 CFR 1	9.15.
E. Reports or notification of	Reports or notification of		were not made in accordance with
10 CFR	or License Condition !	Number	
F			
Annual Control of the			
240073			
			to correct the violations identified in the items checked

SIGNATURE - LICENSEE 9401250160 931214 PDR ADDCK 03009744 C PDR

DATE

SIGNATURE -- NRC INSPECTOR

DATE

12/14/938

TEO