

JAN 13 1994

Ultrasonic Field Services, Corp.
1211 Kona Drive
Rancho Dominguez, California 90220

Attention: William J. DeLuca
Radiation Safety Officer

Please find enclosed an NRC Form-591 which indicates that one violation and one non-cited violation were identified during the safety inspection conducted on January 5-6, 1994, of activities authorized under reciprocity of your State of California License No. 4909-70.

Pursuant to the provisions of 10 CFR 2.202, you are requested, within 30 days, to sign and date the enclosed NRC Form-591 which indicates that appropriate corrective action will be taken with reference to the violation and non-cited violation described on the form. After signing, please detach the first sheet of NRC Form-591 and return the remaining copies with your signature to John Jacobson at the Region V office.

The NRC requires implementation of the Revised 10 CFR Part 20 (20.1001-2401) as of January 1, 1994 for licensees performing licensed activities under NRC jurisdiction. During this inspection the inspectors were informed that your personnel had not yet been trained on changes in NRC requirements in the Revised Part 20. In addition to the items above, we call your attention to the need to review the Revised Part 20 for requirements applicable to your program and provide appropriate training for your personnel.

If you have any questions on this inspection, please telephone John M. Jacobson at (510) 975-0252.

Thank you for your cooperation.

Sincerely,

original signed by

Gregory P. Yuhas, Chief
Radioactive Materials Safety Branch

Enclosure: NRC Form-591

9401250254 940113
REQ5 SUBJ

PDR

IE 07
9/1

bcc w/Encl:
Docket File
Inspection Files
M. Smith
Central Files

RV/cb

REQUEST COPY
YES/NO

JJ
JJacobson
1/12/94

REQUEST COPY
YES/NO

KP
KPrendergast
1/13/94

SEND TO PDR
YES/NO

GY
GYuhas
1/13/94

SEND TO DCS
YES/NO

JD
bloey
yes/NO
1/13/94

IFS Data Entry Form

SPECIFY ALL THAT APPLY

Reviewed By [Signature]
Date 1/10/94

Reactor/Vendor Inspection (IFS Option 1)
 Items Opened (Y/N) _____
 Material Inspection (IFS Option 2)
 B01 (Y/N) Y
 Letter (Y/N) Y
 Clear (Y/N) N
 Docket Related P21 Items (IFS Option 4)
 Enter Log Number _____
 LER Items (IFS Option 5)
 Enter LER Number _____
 Non-Docket Related Items (IFS Option 6)

Site Name Ultrasonic Field Services

Report Transmittal Date _____

Lead Inspector 5330

Responsible Org Code 5330

Report End Date _____

Region V

Report NBR 94-01
 A _____
 B _____
 C _____
 Docket NBR 150-00004

Materials Only
 License NBR 4909-70 (CA)

Update? (Y/N): N Opened IRLERP21 LOG/IFS Number: _____

***Sequence NBR: 01 Item Type: NCV **Severity: _____ **Supplement: _____
 Status *UPD VR *Prof. Closeout *Actual Closeout
 A N _____
 B _____
 C _____

10 CFR <u>19.11, 21.6</u>	Materials Only License Cond.	Tie Down

Title: Failure to post 10 CFR 19, 20, 21, procedures and section 2065 (55 character width)
 Closeout Org _____ *Closeout EMP. _____ *Contact EMP. _____ *Procedure: _____ *Fundl Area: _____
 *Cause CD: _____ **EA Number: _____ **NOV/NCC Issue Date: 1/1

Text: The licensee failed to post copies of 10 CFR 19, 20, 21, procedures, and section 2065 of Energy Reorganization Act, or a notice in either its radiography vehicle or at its place of business.

Update? (Y/N): _____ Opened IRLERP21 LOG/IFS Number: _____

***Sequence NBR: 02 Item Type: VIO **Severity: 4 **Supplement: 5
 Status *UPD VR *Prof. Closeout *Actual Closeout
 A 0 _____
 B _____
 C _____

10 CFR <u>71.12</u>	Materials Only License Cond.	Tie Down

Title: Failure to register Type B package and obtain QA program approval (55 character width)
 Closeout Org _____ *Closeout EMP. _____ *Contact EMP. _____ *Procedure: _____ *Fundl Area: _____
 *Cause CD: _____ **EA Number: _____ **NOV/NCC Issue Date: 1/1

Text: _____

* Optional Fields.
 ** Severity, Supplement, and NOV/NCC only applicable for Violations. EA Number only applicable for Escalated Enforcement Items.
 *** Sequence NBR is not applicable for docket related P21, LER, or non-docket related items.

ITEMS CONTINUED? (Y/N): N