

# SAFETY INSPECTION

1. LICENSEE Ultrasonic Field Services 1211 Kona Drive Rancho Dominguez, CA 90220		2. REGIONAL OFFICE REGION V U S NUCLEAR REGULATORY COMMISSION 1450 MARIA LANE SUITE 210 WALNUT CREEK CA 94596-5368	
3. DOCKET NUMBER(S)  150-00004	4. LICENSE NUMBER(S)  4909-70 (California)	5. DATE OF INSPECTION  January 5-6, 1994	

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.
  - A. \_\_\_\_\_ was not properly posted to indicate the presence of a \_\_\_\_\_, 10 CFR 20.203(b),(c),(d),(e) or 34.42.
  - B. \_\_\_\_\_ of sealed sources were not performed at the proper frequencies. 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
  - C. Records of \_\_\_\_\_ were not properly maintained. 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
  - D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
  - E. Reports or notification of \_\_\_\_\_ were not made in accordance with 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
  - F. Failure to submit licensee's name and license number and package identification number and to obtain approval of the quality assurance program prior to use of the package as required by 10 CFR 71.12.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE 9401250259 940113 REG5 SUBJ PDR		DATE	SIGNATURE - NRC INSPECTOR <i>John M. Jacobson</i> <i>Kurt M. Prandzy</i>		DATE 1/7/94 1/13/94
---	--	------	--	--	---------------------------

# SAFETY INSPECTION

1. LICENSEE  
 Ultrasonics Field Services  
 1211 Kona Drive  
 Rancho Dominguez, CA 90220

2. REGIONAL OFFICE  
 REGION V  
 U S NUCLEAR REGULATORY COMMISSION  
 1450 MARIA LANE SUITE 210  
 WALNUT CREEK CA 94596-5368

3. DOCKET NUMBER(S)  
 150-00004

4. LICENSE NUMBER(S)  
 4909-70 (California)

5. DATE OF INSPECTION  
 January 5-6, 1994

3. (Continued)

G.

H.

I.

4. The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

A. Failure to post copies of 10 CFR Parts 19, 20, 21, section 206 of the Energy Reorganization Act, and procedures or a notice indicating where the documents may be examined as required by 10 CFR 19.11 and 21.6.

B.

C.