

Atomics International Division
Rockwell International

Docket No. 70-25
License No. SNM-21

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on January 13-17, 1975, it appears that certain of your activities were not conducted in full compliance with the conditions of your NRC License No. SNM-21.

Violations

None.

Infractions

None.

Deficiencies

1. Contrary to License Condition 3.1 and 10 CFR 70.51(f)(3)(1), not all material inventoried was listed at measured values. Some items were carried at nominal values on the inventory, and six (6) waste drums were not measured.

The use of nominal values was identified by the licensee. The six (6) unmeasured waste drums were identified by an NRC inspector during the records audit.

IE-V-17 Copy No. 16

10 ~~CFR 2750 INFORMATION~~